

PService
Version 2.1.1.7

English

1 Abstract

This document contains information on news and changes that are introduced with the current version of the software. Additionally it gives an overview on the tested and supported functional range of the various software versions.

2 Validity

This document applies to the software **PService**. It has been created on basis of the software version 2.1.1.7.

3 Compatibility

The software **PService** is compatible with the following hard- and software after the update to the current version:

- Operating system Windows*) XP SP3
- Operating system Windows 7 (32 / 64 Bit)
- PC with CPU Intel Core2Duo 2,0 GHz and 2 GB working memory (or similar)
- Router / switch with broadcast support

4 Notes

Note that

- this update is free of charge.
- the innovations are only generally described in this document.
- the use of some functions may require a license subject to charges.
- the Dallmeier support hotline always is available for further questions.

5 Procedure

The update from version 2.0.1.12 to version 2.1.1.7 is available in the Dallmeier Partner Forum on the corresponding product page (Products > Software > PService). The update is done by installing version 2.1.1.7 in the existing installation directory. Existing settings and configurations are adopted.

6 Innovations

Network Interfaces

Description	<p>The current version of the software PService has been extended for the installation on devices with several network interfaces. This allows the convenient configuration and administration of VideoIP systems in separated networks.</p> <p>The configuration of the various network interfaces is made in the dialogue Edit > System > Network settings. The selection of the currently used network interface is made with a drop down box in the IP finder window (left side of the Scanning button).</p>		
Availability	X	Update	X Installation ex factory
Hardware		Necessary	X Not necessary
Requirements	Device with several network interfaces		

SMAVIA Appliances

Description	<p>The current version of the software PService supports all SMAVIA appliances with version 8.1.1 or higher of the preinstalled SMAVIA Recording Server:</p> <ul style="list-style-type: none"> • DMS 2400 • DLS 1600 • IPS 2400 		
Availability	x	Update	X Installation ex factory
Hardware		Necessary	x Not necessary
Requirements	SMAVIA Recording Server (preinstalled) as of version 8.1.1		

Maintenance License

Description	<p>As a new function PService now is able to request information about the maintenance license from SMAVIA appliances. The display of the information can be activated via the tool bar or via the Context menu > SW-Maintenance information after the selection of the appliance.</p>		
Availability	X	Update	X Installation ex factory
Hardware		Necessary	X Not necessary
Requirements			

Localisation

Description	<p>Now the display of the user interface in Russian is supported besides English and German. The setting of the required language is made in the dialogue Option > Language.</p>		
Availability	X	Update	X Installation ex factory
Hardware		Necessary	X Not necessary
Requirements			

7 Functional Range

The use of some functions may require a license subject to charges. Always observe the corresponding specifications of the software.

	2.0.1.12	2.1.1.7						
Support of several network interfaces	O	X						
Support of SMAVIA appliances	O	X						
Russian localisation	O	X						

X = Function is available in version

O = Function is not available in version

Dallmeier electronic GmbH & Co.KG
Cranachweg 1
93051 Regensburg
Germany

Tel.: +49 (0) 941 87 00-0
Fax: +49 (0) 941 87 00-180
www.dallmeier.com